



## NT DRILL CHUCK ARBOR




When ordering, please do clearly specify either Whit Or Metric DRAW BAR THREADS desired.

TYPE	D	d <sub>1</sub>	L	l <sub>1</sub>	l <sub>2</sub>	1/2" W12 or M12 x 1.75P 5/8" W11 or M16 x 2.0P
NT30 x JT6	49	31.75	111	68.4	18.6	
NT40 x JT6	63	44.45	138	93.4	20.6	



## MILLING MACHINE ADAPTOR



When you are ordering this product, be sure to tell us the DRAW BAR SIZE you are going to use.

SIZE	l <sub>1</sub>	D	d <sub>1</sub>	d <sub>2</sub>	d <sub>3</sub>	d <sub>4</sub>	L	a	T
NT30 x MTA3	65	49	31.75	40	17.15	23.825	133.4	1.6	1/2" W12 M12 x 1.75P
NT40 x MTA3	65	63	44.45	40	25.07	23.825	158	1.6	5/8" W11 or M16 x 2.0P